

16
8/11/15

Near Bank

ORP 9.6 mV
DO 5.50 mg/L
Temp 19.01 °C
Conductivity 328 µS/cm
pH 7.88

Turbidity 72.6 NTU

1135 Collect Sediment Sample LUW-030-150811-51

1145 Collect Surface Water Sample

LUW-030-150811-11 - Collected ~12' From the
Bank. TSS/TDS/TAL Metals/Dissolved TAL
Metals/pH/Alkalinity/Anions

1200 Depart for FW-040.

1240 Arrive at FW-040. Prepare to collect
Surface Water Quality Data/Sample

Near Bank

Temp 22.52 °C

pH 8.62

Turbidity 12.4 NTU

ORP 364 mV

Conductivity 360 µS/cm

DO 5.13 mg/L

1300 Collect Sediment Sample FW-040-150811-51

1305 Collect Surface Water Sample

FW-040-150811-11 - Collected ~12' From

~12' From Bank

59.4 mV
5.50 mg/L
18.91 °C

335 µS/cm

7.93

74.5 NTU

From
DIS

~12' From Bank

22.04 °C

8.37

10.8 NTU

261 mV

347 µS/cm

5.32 mg/L